

112 年北投焚化廠戴奧辛委外檢測一覽表

年度	日期	爐號	採樣機構	分析機構	檢測結果 (ng-TEQ/Nm ³)	標準值 (ng-TEQ/Nm ³)
112	3月8日 至 3月9日	4	九連環境開發股份有限公司	九連環境開發股份有限公司	0.018	0.1
	7月26日 至 7月27日	1	九連環境開發股份有限公司	九連環境開發股份有限公司	0.035	
	8月4日 及 8月7日	3	九連環境開發股份有限公司	九連環境開發股份有限公司	0.013	
	8月23日 及 8月25日	2	九連環境開發股份有限公司	九連環境開發股份有限公司	0.026	

註：依據「廢棄物焚化爐戴奧辛管制及排放標準」第8條及規定，焚化爐每年應定期檢測煙道排氣中戴奧辛污染物2次。另因北投廠共有4個焚化爐均為相同型式及操作規模，依法每半年須擇1座焚化爐進行戴奧辛檢測（4擇1），即每年須完成2座焚化爐之戴奧辛檢測。北投廠以優於法規之標準，每年完成4座焚化爐之戴奧辛檢測，故北投廠內4個爐每爐每年均會執行1次檢測。

The Result of Outsourcing Detection of Dioxin Pollutants in Stack Emission in ROC 112

Year	date	Incinerator Number	Sampling institution	Detection institution	Result (ng-TEQ/Nm ³)	Emission standard (ng-TEQ/Nm ³)
112	3/8-3/9	No.4	Kyulien Environment Improving Co.,Ltd.	Kyulien Environment Improving Co.,Ltd.	0.018	0.1
	7/26-7/27	No.1	Kyulien Environment Improving Co.,Ltd.	Kyulien Environment Improving Co.,Ltd.	0.035	
	8/4、8/7	No.3	Kyulien Environment Improving Co.,Ltd.	Kyulien Environment Improving Co.,Ltd.	0.013	
	8/23、8/25	No.2	Kyulien Environment Improving Co.,Ltd.	Kyulien Environment Improving Co.,Ltd.	0.026	

Ref: Pursuant to Article 8 of “Waste Incinerator Dioxin Control and Emission Standards” which is enacted by Environmental Protection Administration Executive Yuan in ROC92 AUG 20th, incinerators should conduct twice a year regular tests of dioxin pollutants in stack emissions from ROC 93.